

MISCELLANEOUS

No.222

February 15, 1961

TO ALL ROOTES GROUP DEALERS

TIRE PRESSURES

SUNBEAM ALPINE

We have had an isolated number of complaints from Dealers and owners relative to a thumping condition in connection with tires fitted to Alpine models.

While this could not be isolated to Alpine vehicles alone it could be equally common to any vehicles in that long storage at deflated tire pressures could have a profound influence on tires being out of round or causing flat spots.

To eliminate these problems it is suggested that tires be inflated to 35 p.s.i. for a short period of time when the tire will reform to the desired circumference, and if the vehicle is then to be operated continually the tire pressures should be reduced to that specified in the Owner's Handbook or increased as local conditions warrant.

Kindly bring the above to the attention of all concerned.

ROOTES MOTORS INCORPORATED



F. J. McGettrick
Manager
Wholesale Parts & Service Depts.

FJMcG:SO